


Optional: Use Soldering iron to make holes for easy installation and access



Note correct propeller direction

